



## Meritor CVA Europe Core Policy

All Products	% Deduction
Damage by non-operational causes such as fire, excessive rust due to improper storage, damage due to poor handling, disassembly	100%
Product not in an active core group within the Meritor product range	100%
Missing Components	50%
<b>Carriers</b>	
Adjusting ring missing or damaged thread	50%
Damaged spigot bore	50%
Spin out core	50%
Disassembled core with all parts present	25%
Two or more deductions	100%
<b>Calipers</b>	
Broken or cracked housing	50%

### Examples



Credit- complete Meritor caliper



Credit - Missing component



Credit - Damage by non-operational causes

Cores with deduction will be available for inspection for a maximum of two weeks after the end of the month of return.

For more information, please contact Customer Service on +44 (0) 1527 503950 or email [core2@meritor.com](mailto:core2@meritor.com).