

Turbocharger

Criteria:

Identification

Completeness

Mechanical damage

Corrosion



Identification

Part number on housing




Completeness

Part can not be incomplete or dismantled.
Missing wastegate, actuator, manifolds and blow off valve is not acceptable



Mechanical damage

Broken housing, shaft, other visible turbine or compressor wheel damage is not acceptable



Corrosion

Corrosion is acceptable



**For further questions, please
contact your local Skuba dealer**

